



Legislation Details (With Text)

File #: 20-1536 **Version:** 1 **Name:**

Type: CONSENT AGENDA **Status:** Approved

File created: 8/7/2020 **In control:** Water Utilities Department

On agenda: 11/11/2020 **Final action:** 11/11/2020

Title: Authorize Supplemental Agreement No. 1 to the professional services contract with Garver, LLC to provide additional engineering services required for investigation, preliminary design, development of construction plans and specifications, and bid phase services for the Kidd Springs Drainage Tunnel Rehabilitation - Not to exceed \$89,945.00, from \$886,940.13 to \$976,885.13 - Financing: Storm Drainage Management Capital Construction Fund

Sponsors:

Indexes: 1

Code sections:

Attachments: 1. Map, 2. Resolution

Date	Ver.	Action By	Action	Result
------	------	-----------	--------	--------

STRATEGIC PRIORITY: Mobility Solutions, Infrastructure, and Sustainability

AGENDA DATE: November 11, 2020

COUNCIL DISTRICT(S): 1

DEPARTMENT: Water Utilities Department

EXECUTIVE: Majed Al-Ghafry

SUBJECT

Authorize Supplemental Agreement No. 1 to the professional services contract with Garver, LLC to provide additional engineering services required for investigation, preliminary design, development of construction plans and specifications, and bid phase services for the Kidd Springs Drainage Tunnel Rehabilitation - Not to exceed \$89,945.00, from \$886,940.13 to \$976,885.13 - Financing: Storm Drainage Management Capital Construction Fund

BACKGROUND

On June 12, 2019, City Council authorized a professional services contract with Garver, LLC for the engineering design of three storm drainage improvement projects at Coombs Creek adjacent to 1641 Junior Drive, Lisbon Area C, and Pleasant Branch. In the course of performing engineering efforts to replace a failed section of storm sewer outfall and box culvert near 1641 Junior Drive, a visual inspection of the drainage tunnel further upstream was conducted. Portions of the existing 8-foot wide horseshoe drainage tunnel were found to be in poor condition with evidence of infiltration, corrosion, and degradation of the concrete material.

OWNER

Garver, LLC

Brock Hoskins, President

MAP

Attached