



LANDMARK COMMISSION

July 6, 2026

FILE NUMBER: COA-26-000266
LOCATION: 400 N Willomet Ave
STRUCTURE: Contributing
COUNCIL DISTRICT: 1

PLANNER: Christina Paress
DATE FILED: May 21, 2026
DISTRICT: Winnetka Heights (H-15)

APPLICANT: Lauren Low

REPRESENTATIVE: N/A

OWNER: Lauren Low

REQUEST(S):

A Certificate of Appropriateness to replace nine (9) aluminum windows with clad composite windows on a main structure.

STAFF RECOMMENDATION:

That the Certificate of Appropriateness to replace nine (9) aluminum windows with clad composite windows on a main structure be approved with the conditions that the replacement windows are all wood no cladding, one over one lite configuration, and to be approved by staff prior to replacement. Implementation of the conditions will allow the proposed work to be consistent with preservation criteria Sec. 51P-87.111(a)(17); meet the standards in City Code Section 51A-45.501(g)(6)(c)(i) for contributing structures; and the Secretary of the Interior's Standards for Rehabilitation.

TASK FORCE RECOMMENDATION:

That the Certificate of Appropriateness to replace nine (9) aluminum windows with Renewal by Anderson windows on main structure be approved with following the conditions: 1. that proposed windows are all wood, cannot be clad, and make sure bottom rail is wider, i.e. Marvin Heritage profile, 2. submit additional photos to prove windows are aluminum, and 3. only replace aluminum windows and paint to match existing.

BACKGROUND / HISTORY:

RELEVANT PRESERVATION CRITERIA:

1. Winnetka Heights Historic District (H-15); Ordinance No. 87
2. Secretary of the Interior's Standards/Guidelines for Setting (District / Neighborhood)
 - **Recommended:** Identifying, retaining, and preserving building and landscape features that are important in defining the overall historic character of the setting. Such features

can include circulation systems, such as roads and streets; furnishings and fixtures, such as light posts or benches; vegetation, gardens and yards; adjacent open space, such as fields, parks, commons, or woodlands; and important views or visual relationships.

- **Not Recommended:** Removing or substantially changing those building and landscape features in the setting which are important in defining the historic character so that, as a result, the character is diminished.
- **Not Recommended:** Introducing a new building or landscape feature that is visually or otherwise incompatible with the setting's historic character (e.g., replacing low metal fencing with a high wood fence).
- **Not Recommended:** Removing a character-defining feature of the building or landscape from the setting that is unrepairable and not replacing it or replacing it with a new feature that does not match.


3. City Code Section 51A-4.501(g)(6)(C)(i):

*The landmark commission must grant the application if it determines that:
(i) for contributing structures:*

LOCATION MAPS

400 N Willomet Ave

Source: Google Map



CURRENT PHOTOS
400 N Willomet Ave



CONTEXT PHOTOS
400 N Willomet Ave





ATTACHMENTS:

- **Task Force Recommendation Form**
- **Current Drawings**

**TASK FORCE
RECOMMENDATION(S)**

TASK FORCE RECOMMENDATION REPORT
Winnetka Heights and Lake Cliff Historic Districts

DATE: 6/10/2026
TIME: 4:00 p.m.
LOCATION: Hybrid Virtual/2922 Swiss Ave

Applicant Name: Lauren Tanner
Address: 400 N Willomet Ave
Request Type: CA

Request: *Replace 9 windows (currently aluminum)*

Recommendation: *all wood windows*

Approve Approve with conditions Deny w/o prejudice Deny

Comments: *must select all wood windows - cannot be clad*
- make bottom rail wider - ex: Marvin heritage profile
- add pictures that prove windows are aluminum
- only replace aluminum windows

Task force members present: *- paint to match existing*

Christine Escobedo Alfred Pena (Vice-chair)
 Mia Ovcina Troy Sims
 Caitlin Parish Michelle Walker (Chair)

Ex Officio staff members present: Christina Paress

Quorum: Yes No (four makes a quorum) *3?*

Maker: *Fred* 2nd: *Michelle*

FOR: *all* AGAINST: *—*

Basis for opposition:

**APPLICATION FOR
CERTIFICATE OF APPROPRIATENESS**




Quote

DBA: RENEWAL BY ANDERSEN OF NORTH TEXAS
 Legal Name: North Texas Windows and Doors LLC
 1215 West Crosby Rd, Suite 180 | Carrollton, TX 75006
Jeffrey Johnson (214)315-5269

Lauren & Brent Low
 400 N Willomet Ave
 Dallas, TX 75208
 (409)594-5259

| ID#: | ROOM: | SIZE: | IMAGE: | DETAILS: |
|------------|--------|--------------|--------|--|
| | | | | Misc: Misc, All Job Miscellaneous Charges, Processing Fee, Quantity 1, |
| | | | | Misc: Misc, All Job Miscellaneous Charges, Lead Testing, Quantity 1, |
| 101 | Room 1 | 43 W 65 H | | Window: Acclaim™ Double-Hung (DG) , Reverse Cottage 3:2, Limited Travel Reduced 6.5625, Flat Sill, Base Frame, Modern Checkrail, Exterior White, Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White , Standard Color Extra Lock Screen: TruScene , Full Screen Grille Style: No Grille Misc: None |
| 102 | Living | 23 W 65 H | | Window: Acclaim™ Casement Single , Right, Base Frame, Exterior White, Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Screen: TruScene , Full Screen Grille Style: No Grille Misc: None |
| 103 | Living | 33 W 65 H | | Window: Acclaim™ Picture , Base Frame, Exterior White, Interior White Performance Calculator: PG Rating: 50 DP Rating: + 50 / - 50 Glass: All Sash: High Performance SmartSun Glass, No Pattern Grille Style: No Grille Misc: None |

104 Living 23 W 65 H  **Window:** Acclaim™ Casement Single , Left, Base Frame, Exterior White, Interior White **Performance Calculator:** PG Rating: 40 | DP Rating: + 40 / - 40 **Glass:** All Sash: High Performance SmartSun Glass, No Pattern **Hardware:** White **Screen:** TruScene , Full Screen **Grille Style:** No Grille **Misc:** None

121 Kitchen 33 W 64 H  **Window:** Acclaim™ Double-Hung (DG) , Reverse Cottage 3:2, Flat Sill, Base Frame, Modern Checkrail, Exterior White, Interior White **Performance Calculator:** PG Rating: 40 | DP Rating: + 40 / - 40 **Glass:** All Sash: High Performance SmartSun Glass, No Pattern **Hardware:** White , Standard Color Extra Lock **Screen:** TruScene , Full Screen **Grille Style:** No Grille **Misc:** None

122 Kitchen 33 W 64 H  **Window:** Acclaim™ Double-Hung (DG) , Reverse Cottage 3:2, Flat Sill, Base Frame, Modern Checkrail, Exterior White, Interior White **Performance Calculator:** PG Rating: 40 | DP Rating: + 40 / - 40 **Glass:** All Sash: High Performance SmartSun Glass, No Pattern **Hardware:** White , Standard Color Extra Lock **Screen:** TruScene , Full Screen **Grille Style:** No Grille **Misc:** None

124 Twins' Room 33 W 65 H  **Window:** Acclaim™ Double-Hung (DG) , Reverse Cottage 3:2, Flat Sill, Base Frame, Modern Checkrail, Exterior White, Interior White **Performance Calculator:** PG Rating: 40 | DP Rating: + 40 / - 40 **Glass:** All Sash: High Performance SmartSun Glass, No Pattern **Hardware:** White , Standard Color Extra Lock **Screen:** TruScene , Full Screen **Grille Style:** No Grille **Misc:** None

125 Twins' Room 33 W 65 H  **Window:** Acclaim™ Double-Hung (DG) , Reverse Cottage 3:2, Flat Sill, Base Frame, Modern Checkrail, Exterior White, Interior White **Performance Calculator:** PG Rating: 40 | DP Rating: + 40 / - 40 **Glass:** All Sash: High Performance SmartSun Glass, No Pattern **Hardware:** White , Standard Color Extra Lock **Screen:** TruScene , Full Screen **Grille Style:** No Grille **Misc:** None

126 Twins' Room 33 W
65 H



Window: Acclaim™ Double-Hung (DG) , Reverse Cottage 3:2,
Flat Sill, Base Frame, Modern Checkrail, Exterior White,
Interior White **Performance Calculator:** PG Rating: 40 | DP
Rating: + 40 / - 40 **Glass:** All Sash: High Performance
SmartSun Glass, No Pattern **Hardware:** White , Standard
Color Extra Lock **Screen:** TruScene , Full Screen **Grille Style:**
No Grille **Misc:** None

WINDOWS: 9 PATIO DOORS: 0 ENTRY DOORS: 0 SPECIALTY: 0 MISC: 2



*Renewal by Andersen is committed to our customers' safety by
complying with the rules and lead-safe work practices specified by the EPA.*



DBA: RENEWAL BY ANDERSEN OF NORTH TEXAS
Legal Name: North Texas Windows and Doors LLC
1215 West Crosby Rd, Suite 180 | Carrollton, TX 75006
Phone: 817-841-1416 | Fax: (null) | contracts@ASmarterWindow.com

Lauren & Brent Low
400 N Willomet Ave
Dallas, TX 75208
H: (409)594-5259

Thank you for your order

Please find, enclosed for your convenience, the contents of your agreement with North Texas Windows and Doors LLC d/b/a Renewal by Andersen of North Texas

Table of Contents

| | |
|--|----|
| Home Improvement Agreement and Payment Terms | 2 |
| Itemized Order Receipt | 3 |
| Notice of Cancellation | 6 |
| Lifetime Labor Warranty.pdf | 8 |
| New Acclaim Warranty .pdf | 10 |
| Terms and Conditions of Sale | 12 |
| Sales Cost Savings Program (SCSP) | 15 |
| What to Expect | 16 |
| Disclosure Statement | 18 |
| Lead-safe Form | 21 |
| Release Agreement | 22 |
| Price Presentation Discounts | 24 |



Home Improvement Agreement and Payment Terms

DBA: RENEWAL BY ANDERSEN OF NORTH TEXAS
Legal Name: North Texas Windows and Doors LLC
1215 West Crosby Rd, Suite 180 | Carrollton, TX 75006
Phone: 817-841-1416 | Fax: (null) | contracts@ASmarterWindow.com

Lauren & Brent Low
400 N Willomet Ave
Dallas, TX 75208
H: (409)594-5259

Lauren & Brent Low

05/14/26

BUYER(S) NAME

CONTRACT DATE

400 N Willomet Ave, Dallas, TX 75208

(409)594-5259

BUYER(S) STREET ADDRESS

PRIMARY NUMBER

SECONDARY NUMBER

laurenlow104@gmail.com

PRIMARY EMAIL

SECONDARY EMAIL

NOTES:

Buyer(s) hereby jointly and severally agrees to purchase the products and/or services of North Texas Windows and Doors LLC d/b/a Renewal by Andersen of North Texas("Contractor"), in accordance with the terms and conditions described in this Home Improvement Agreement and Payment Terms, any documents listed in the Table of Contents, and any other document attached to this Home Improvement Agreement, the terms of which are all agreed to by the parties and incorporated herein by reference (collectively, this "Agreement"). Buyer(s) hereby agrees to sign a completion certificate after Contractor has completed all work under this Agreement.

| | | | |
|------------------------------|-----------|---|-----------------------------------|
| TOTAL CONTRACT PRICE: | \$27,996 | By signing this Agreement, you acknowledge that the Balance Due, and the Amount Financed must be made by personal check, bank check, credit card, or cash. | |
| DOWN PAYMENT: | \$0 | | |
| BALANCE DUE: | \$27,996 | Estimated Start: 3-5 months | Estimated Completion: 1-2 days |
| AMOUNT FINANCED: | \$27,996 | | |
| METHOD OF PAYMENT: | Financing | We schedule installations based on the date of the signed contract and secondarily on the date in which we complete the technical measurements. The installation date that we are providing at this time is only an estimate. We will communicate an official date and time at a later date. Rain and extreme weather are the most common causes for delay. | |

NOTES:

Buyer(s) agrees and understands that this Agreement constitutes the entire understandings between the parties and that there are no verbal understandings changing or modifying any of the terms of this Agreement. No alterations to or deviations from this Agreement will be valid without the signed, written consent of both the Buyer(s) and Contractor. Buyer(s) hereby acknowledges that Buyer(s) 1) has read this Agreement, understands the terms of this Agreement, and has received a completed, signed, and dated copy of this Agreement, including the two attached Notices of Cancellation, on the date first written above and 2) was orally informed of Buyer's right to cancel this Agreement.

NOTICE TO BUYER: Do not sign this contract if blank. You are entitled to a copy of the contract at the time you sign.

YOU, THE BUYER, MAY CANCEL THIS TRANSACTION AT ANY TIME NOT LATER THAN MIDNIGHT OF 05/18/2026 OR THE THIRD BUSINESS DAY AFTER THE DATE OF THIS TRANSACTION, WHICHEVER DATE IS LATER. SEE THE ATTACHED NOTICE OF CANCELLATION FORM FOR AN EXPLANATION OF THIS RIGHT.

SIGNATURE OF SALES PERSON:

SIGNATURE OF CUSTOMER 1:

SIGNATURE OF CUSTOMER 2:

Jeffrey Johnson

Lauren Low

Brent Low

PRINT NAME OF SALES PERSON

PRINT NAME

PRINT NAME



Itemized Order Receipt

DBA: RENEWAL BY ANDERSEN OF NORTH TEXAS
 Legal Name: North Texas Windows and Doors LLC
 1215 West Crosby Rd, Suite 180 | Carrollton, TX 75006
 Phone: 817-841-1416 | Fax: (null) | contracts@ASmarterWindow.com

Lauren & Brent Low
 400 N Willomet Ave
 Dallas, TX 75208
 H: (409)594-5259

| ID#: | ROOM: | SIZE: | DETAILS: | PRICE: |
|------------|--------|--------------|--|--------|
| | | 0 W 0 H | Misc: Misc, All Job Miscellaneous Charges, Processing Fee, Quantity 1 | |
| | | 0 W 0 H | Misc: Misc, All Job Miscellaneous Charges, Lead Testing, Quantity 1 | |
| 101 | Room 1 | 43 W 65 H | Window: Acclaim™ Double-Hung (DG) Reverse Cottage 3:2 Limited Travel Reduced 6.5625 Flat Sill, Base Frame Modern Checkrail Exterior White Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Standard Color Extra Lock Screen: TruScene Full Screen Grille Style: No Grille Misc: None | |
| 102 | Living | 23 W 65 H | Window: Acclaim™ Casement Single Right Base Frame Exterior White Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Screen: TruScene Full Screen Grille Style: No Grille Misc: None | |
| 103 | Living | 33 W 65 H | Window: Acclaim™ Picture Base Frame Exterior White Interior White Performance Calculator: PG Rating: 50 DP Rating: + 50 / - 50 Glass: All Sash: High Performance SmartSun Glass, No Pattern Grille Style: No Grille Misc: None | |
| 104 | Living | 23 W 65 H | Window: Acclaim™ Casement Single Left Base Frame Exterior White Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Screen: TruScene Full Screen Grille Style: No Grille Misc: None | |



Itemized Order Receipt

DBA: RENEWAL BY ANDERSEN OF NORTH TEXAS
 Legal Name: North Texas Windows and Doors LLC
 1215 West Crosby Rd, Suite 180 | Carrollton, TX 75006
 Phone: 817-841-1416 | Fax: (null) | contracts@ASmarterWindow.com

Lauren & Brent Low
 400 N Willomet Ave
 Dallas, TX 75208
 H: (409)594-5259

| ID#: | ROOM: | SIZE: | DETAILS: | PRICE: |
|------------|-------------|--------------|--|--------|
| 121 | Kitchen | 33 W 64 H | Window: Acclaim™ Double-Hung (DG) Reverse Cottage 3:2 Flat Sill, Base Frame Modern Checkrail Exterior White Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Standard Color Extra Lock Screen: TruScene Full Screen Grille Style: No Grille Misc: None | |
| 122 | Kitchen | 33 W 64 H | Window: Acclaim™ Double-Hung (DG) Reverse Cottage 3:2 Flat Sill, Base Frame Modern Checkrail Exterior White Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Standard Color Extra Lock Screen: TruScene Full Screen Grille Style: No Grille Misc: None | |
| 124 | Twins' Room | 33 W 65 H | Window: Acclaim™ Double-Hung (DG) Reverse Cottage 3:2 Flat Sill, Base Frame Modern Checkrail Exterior White Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Standard Color Extra Lock Screen: TruScene Full Screen Grille Style: No Grille Misc: None | |
| 125 | Twins' Room | 33 W 65 H | Window: Acclaim™ Double-Hung (DG) Reverse Cottage 3:2 Flat Sill, Base Frame Modern Checkrail Exterior White Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Standard Color Extra Lock Screen: TruScene Full Screen Grille Style: No Grille Misc: None | |
| 126 | Twins' Room | 33 W 65 H | Window: Acclaim™ Double-Hung (DG) Reverse Cottage 3:2 Flat Sill, Base Frame Modern Checkrail Exterior White | |



Itemized Order Receipt

DBA: RENEWAL BY ANDERSEN OF NORTH TEXAS
Legal Name: North Texas Windows and Doors LLC
1215 West Crosby Rd, Suite 180 | Carrollton, TX 75006
Phone: 817-841-1416 | Fax: (null) | contracts@ASmarterWindow.com

Lauren & Brent Low
400 N Willomet Ave
Dallas, TX 75208
H: (409)594-5259

| ID#: | ROOM: | SIZE: | DETAILS: | PRICE: |
|----------------------|-----------------------|-----------------------|--|-----------------|
| | | | Interior White Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: White Standard Color Extra Lock Screen: TruScene Full Screen Grille Style: No Grille Misc: None | |
| WINDOWS: 9 | PATIO DOORS: 0 | ENTRY DOORS: 0 | SPECIALTY: 0 | MISC: 2 |
| PROJECT TOTAL | | | | \$27,996 |



Renewal by Andersen is committed to our customers' safety by complying with the rules and lead-safe work practices specified by the EPA.



Price Presentation Discounts

DBA: RENEWAL BY ANDERSEN OF NORTH TEXAS
Legal Name: North Texas Windows and Doors LLC
1215 West Crosby Rd, Suite 180 | Carrollton, TX 75006
Phone: 817-841-1416 | Fax: (null) | contracts@ASmarterWindow.com

Lauren & Brent Low
400 N Willomet Ave
Dallas, TX 75208
H: (409)594-5259

PROJECT PRICE BEFORE DISCOUNTS

\$36,836

INDIVIDUAL SAVINGS BASED ON 9 UNITS

Advertised Offer

20% Off Project

Savings:

\$7,367

Sales Cost Savings Program (5%)

Savings:


\$1,473

TOTAL PRICE: \$27,996


\$8,840
SAVINGS

Viewing Project Details For:

04784629

 400 N Willomet Ave,
Dallas, Texas 75208

Product Summary

 Images may not reflect the exact product ordered




Acclaim® Double-Hung Window-DG

Room 1
Unit Id: 101
Interior Color: White
Exterior Color: White
[View more](#)




Acclaim® Casement Window

Living
Unit Id: 102
Interior Color: White
Exterior Color: White
[View more](#)



Payment Summary

| | |
|--------------------------|---------------------|
| Investment total | \$27,996.00 |
| Subtotal | \$27,996.00 |
| Payment applied | -\$13,998.00 |
| <hr/> | |
| Balance Remaining | \$13,998.00 |

 To make a Payment, please call our office at 469-320-9185 during the hours of 8AM - 5PM Monday - Friday.

Previous Payments

| | |
|------------------------|-------------------|
| Payment Details | 05/19/2026 |
| Amount | -\$13,998.00 |
| Method | ACH - Greensky |

Need any assistance?

Acclaim® Picture Window - Universal

Living

Unit Id: 103

Interior Color: White

Exterior Color: White

[View more](#)



Acclaim® Casement Window

Living

Unit Id: 104

Interior Color: White

Exterior Color: White

[View more](#)



Acclaim® Double-Hung Window-DG

Kitchen

Unit Id: 121

Interior Color: White

Exterior Color: White

[View more](#)



Acclaim® Double-Hung Window-DG

Kitchen

Unit Id: 122

Interior Color: White

Exterior Color: White

[View more](#)



Acclaim® Double-Hung Window-DG

Twins' Room

Unit Id: 124

Interior Color: White

Exterior Color: White

[View more](#)



Acclaim® Double-Hung Window-DG

Twins' Room

Unit Id: 125

Interior Color: White

Exterior Color: White

[View more](#)



Acclaim® Double-Hung Window-DG

Twins' Room

Unit Id: 126

Interior Color: White

Exterior Color: White

[View more](#)

Store Location Defined 29

Unit Id:

Store Location Defined 28

Unit Id:

North Texas Windows and Doors, LLC

Administrative offices

1215 W Crosby Rd Suite 180

Carrollton, Texas 75006

(214) 545-0612 (tel:(214) 545-0612)

Products & Services

Replacement Windows (<https://www.renewalbyandersen.com/replacement-windows/>)

Replacement Doors (<https://www.renewalbyandersen.com/replacement-doors/>)

Commercial Buildings (<https://www.renewalbyandersen.com/commercial/>)

About Us

About Renewal by Andersen (<https://www.renewalbyandersen.com/about/>)

Renewal Cares (<https://www.renewalbyandersen.com/why-renewal/community/renewal-cares/>)

News (<https://www.renewalbyandersen.com/news/>)

Careers (<https://www.renewalbyandersen.com/careers/>)

Environmental Commitment (<https://www.renewalbyandersen.com/about/environmental-commitment/>)

Help & Support

FAQ (<https://www.renewalbyandersen.com/resources/articles/faqs-about-our-window-replacement-process/>)

Lead Safety (<https://www.renewalbyandersen.com/resources/lead-safety/>)

Maintenance or Repair Request (<https://www.renewalbyandersen.com/support/service-request/>)

Warranty (<https://www.renewalbyandersen.com/resources/warranty/>)

Become a Retailer (<https://www.renewalbyandersen.com/resources/become-retailer/>)

Sweepstakes (<https://renewyourhome.featuredpromo.com/>)

Request a Brochure →

Schedule a Consultation →



(<https://www.renewalbyandersen.com/>)



(<https://www.andersenwindows.com/>)



(<https://www.renewalbyandersen.com/news/renewal-by-andersen-energy-star-partner-24/>)

Visit Canadian Site
(<https://www.renewalbyandersen.ca/>)



(<https://www.jdpower.com/a>)

Follow us on

(<https://www.facebook.com/rbacorp>)

(<https://twitter.com/RbACorp>)



(<https://www.linkedin.com/company/renewal-by-andersen/>)

Andersen collects certain categories of personal information. See links for more information.

[Terms](#) [Privacy Policy](#) [Privacy Notice for CA Residents](#) [EEO Policy](#)
[Opt Out of Sale of Personal Information](#)

(<https://www.andersenwindows.com/support/do-not-sell-my-info>)

© 2026 Andersen Corporation. All rights reserved.



Front facade (WEST) - facing Willomet Ave



Caption



Caption





Caption

COA— _____

Date Received: _____

Applicant Name: Lauren Low

Received by: _____


Window Survey Form

| Have | Basic Requirements |
|------|---|
| | 1. Photographs or drawing of each elevation of the structure, with all the window openings on each elevation numbered. |
| | 2. Photographs of each window opening <i>numbered</i> corresponding to the photographs or drawings from #1. |
| | 3. Condition Evaluation of each window (see reverse). |
| | 4. Proposed window design (casement, fixed, etc.) , pattern (3/1, 6/6, 1/1, etc.) , materials (wood, vinyl, clad, etc.), etc. Specify if different for certain openings. |
| | 5. Proposed window product brochure/information that includes the company's depiction or photograph (not wind load information) of actual windows. We need to know what they look like on the exterior. |
| | 6. Other _____ |

ALL window openings on the structure should be assigned a **number** and **described** under the same number on the back of this sheet. Even those not being replaced should be assigned a number, however a photograph of those windows is not necessary, note on the second page that you aren't looking to replace that window number.

Windows in **pairs** or **groupings** should be assigned **separate** numbers. Windows in dormers and small fixed windows *should* also be included, but *not* door sidelights or transoms associated with a door.

On the second page, describe the issues and conditions of *each* window in detail, referring to the specific parts of the window (see diagram to the left). The photographs can be from the interior, exterior, or both. *Additional close-up photographs*, showing evidence of window condition, **MUST** be provided to



| | |
|---|-----------|
| Total Number of Window Openings on the Structure | 35 |
| Number of Historic Windows on the Structure | 0 |
| Number of Existing Replacement/NonHistoric Windows -all windows appear to have been replaced in the 1960s (per Window Assessment) other than #23 which appears to have been replaced in the last 10 years | 35 |
| Number of Windows Completely Missing | 0 |
| Total Number of Windows to be Replaced | 9 |

better document problem areas.

The Planning and Development Department's evaluation and recommendation is based on deterioration/damage to the window unit, and associated trim. Broken glass and windows that are painted shut are not necessarily grounds for approving replacement.

COA— _____

Date Received: _____

Applicant Name: _____ Lauren Low _____

Received by: _____

Window Survey Form—Window Condition Report

| Window # | Window Condition |
|-----------|---|
| 1 *101 | Aluminum- not original; single pane glass 1x1 double hung with grilles, fair condition |
| 2 *124 | Aluminum- not original; single pane glass 1x1 double hung with grilles, fair condition Wear on drip cap & exterior casing |
| 3 | Not replacing |
| 4 | Not replacing |
| 5 | Not replacing |
| 6 *125 | Aluminum- not original; single pane glass 1x1 double hung with grilles, fair condition, water damage on exterior casing and cracking between the casing and siding in lower left corner |
| 7 *126 | Aluminum- not original; single pane glass 1x1 double hung with grilles, poor condition, significant water damage on exterior casing, sill and subsill |
| 8 *121 | Aluminum- not original; single pane glass 1x1 double hung with grilles, fair condition |
| 9 *122 | Aluminum- not original; single pane glass 1x1 double hung with grilles, fair condition, peeling/detachment of sill |
| 10 | Not replacing |
| 11 | Not replacing |

| Window # | Window Condition |
|------------|---|
| 21 | Not replacing |
| 22 | Not replacing |
| 23 | Not replacing |
| 24 | Not replacing |
| 25 | Not replacing |
| 26 | Not replacing |
| 27 | Not replacing |
| 28 | Not replacing |
| 29 | Not replacing |
| 30 *102 | Aluminum- not original; single pane glass 1x1 double hung with grilles, poor condition, significant water damage of exterior casing, siding, sill and subsill |
| 31 *103 | Aluminum- not original; single pane glass 1x1 double hung with grilles, poor |

| | |
|----|----------------------|
| | |
| 12 | Not replacing |
| 13 | Not replacing |
| 14 | Not replacing |
| 15 | Not replacing |
| 16 | Not replacing |
| 17 | Not replacing |
| 18 | Not replacing |
| 19 | Not replacing |
| 20 | Not replacing |

| | |
|------------|---|
| | condition, significant water damage of exterior casing, siding, sill and subsill |
| 32 *104 | Aluminum- not original; single pane glass 1x1 double hung with grilles, poor condition, significant water damage of exterior casing, siding, sill and subsill |
| 33 | Not replacing |
| 34 | Not replacing |
| 35 | Not replacing |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 40 | |

corresponds with window number attached to each window based on the quote from Renewal by Andersen